
## General information

FAT & factory certificates



<sup>1)</sup> Can also be ordered following delivery

 $<sup>^{2)}</sup>$  H $_{2}$ O and 2 other gases

<sup>3)</sup> Special gases are invoiced with a surcharge as required. Orders for factory acceptance (FAT) with customer should be ordered with quantity 1. Orders for certificates can be ordered with quantity ≥ 1.